



Plates 1 & 2 : Bay 13 Spandrel, west wall
Overall views before (above left) and after (above right) consolidation treatments.



Plates 3&4: Details before (above left) and after (above right) treatment. A plaster bridge was built up consolidate vulnerable edges prior to injection grouting.



Plates 5&6: Details of the lower central area, showing the severely delaminated section of painted plaster before (above left) and after (above right) treatment.



Plate 7: Detail (left) after the application of a facing to support the fragile plaster during the grouting and repair process.



Plates 8&9: Details of the upper area of the spandrel, before (above left) and after (above right) treatment. Plaster fillet repairs were applied to delaminating edges and a grout injected into voids in the area to the right of the vertical crack. The large piece of white, later inappropriate repair plaster was removed, to reveal the original painted surface.